


-2018 Jan-Jun Inspection Data


SLP VEHICLE AGE



Jan-Jun 2018


124 Carriers 1,686 Random Inspections

7,000 Pass-2-Load Inspections




■ Total faults ■ Vehicles audited


Jan - Jun 2018 National Fault



Jan - Jun 2018 Vehicle Faults by Type by State



Jan - Jun 2018 National Vehicle Roadworthy 660 Inspections



2018 Maintenance Faults General

- Weeping foot-valves
- Front bumper damaged, cracked, missing reflectors, bolts missing
- Dent in tank, gouge in tanker shell, crack on tank support
- Electrical conduit damaged or loose.
- Static reel out of test.
- Air Leaks
- Irregular tire wear, bald tires, damaged tire wall
- Mudguard damaged.
- Bad air leaks
- Damaged vehicle windscreen
- Chassis corrosion
- Broken bracket (witches hat storage)
- Damaged exhaust shielding
- Fire extinguisher in cab not in bracket
- Light lens crazed
- Cracked fuel tank brackets
- Driver side door handle not working
- Steering wheel padding falling apart
- Breakdown triangles missing

-2016-2018 Inspection Data

2016 - 2018 National "Loading Safety"

250

200

150

100

50

0

Exposed electrical wiring

Vapour hose out of test date

Brake door alarm not audible

Brake door alarm not working


Brake door alarm not fitted

Incorrect exhaust shielding

Drive away protection fault

Dust cap missing or not secured

2016 2017 2018




2016-2018 National "Compliance"

250
200
150
100
50
0

Pass-2-Load label expired DG label expired or missing Safety labels not fitted Fire extinguisher out of date No torch or not working Eyewash not fitted EPG or EIP not compliant Isolation switch wrong place

2016 2017 2018



2016 - 2018 National "Maintenance"

250
200
150
100
50
0

Worn loading valves

Fuel leaks and weeps

Emerg stop not working


Internal valve not working

Maintenance fault

2016 2017 2018



2016 – 2018 National Fault Types



■ 2016
 ■ 2017
 ■ 2018

Vehicles inspected found with a fault %

